

## *UltraBook Technical Tips*

### **Installing Solaris™ 2.5.1/2.6 using Sun™ 1/2x CDRom drive**

#### **Explanation:**

There is a bug in the SCSI driver on the Solaris 2.5.1/2.6 installation CD-ROM that will cause "system panics" when using an old SUN 1/2X CD-ROM drive on the UltraBook.

#### **Solution:**

Power on system and execute 'stop-A' when the memory check begins.  
At the 'ok prompt' type in the following commands:

```
ok " /scsi" select-dev  
ok 0 encode-int " scsi-options" property  
ok boot scdrom
```

\*Note\* There is a space character after each (").